
SHED ROOF FLASHING AT THE PEAK



NOTES:

- -INSTALL HORIZONTAL FLANGE OF METAL FLASHING ON TOP OF SHINGLES; SECURE IN PLACE BUT DO NOT OVERDRIVE THE FASTENERS AND CREATE AN INDENTATION IN THE METAL.
- -LAPS IN THE FLASHING, 2" MINIMUM; APPLY SEALANT BETWEEN THE OVERLAPPING ENDS AND FASTEN TOGETHER.

STEEP SLOPE 30

